Terra-Lok Triumph: King Mesa Gin's Solution to Water Intrusion Secures Organic Cotton Harvest

King Mesa Gin in Lamesa, Texas, faced significant water intrusion in the basement's "press pit,"

About The Project		
Contractor	Location	Product Used
WTX Foundation Repair	Lamesa, TX	Terra-Lok™ 24-120

Learn More About Terra-Lok™ 24-120

This case study was featured in <u>Waterproof Magazine</u>.

Problem: **King Mesa Gin** in Lamesa, Texas, faced significant water intrusion in the basement's "press pit," threatening the safety of its personnel and the integrity of its equipment and products. As a major producer of certified U.S. organic cotton, resolving this issue was crucial before the upcoming harvest.

Solution: King Mesa Gin enlisted <u>WTX Foundation Repair</u> from Amarillo, Texas, and <u>Earth Contact Products</u> from Olathe, Kansas, to tackle the problem. After evaluating the damage caused by fluctuating water levels over the years, the teams chose the <u>NCFI Geotechnical</u> polyurethane <u>Terra-Lok™ 120</u> for the job. This solution involved injecting over 400 gallons of Terra-Lok™ to form a monolithic <u>waterproof barrier</u> along the walls of the press pit. Although initial plans included sealing the floor, unforeseen complexities with the double-slab concrete structure shifted the focus to the walls only in the project's

first phase. The discovery of further seepage led to a second phase where the team sealed gaps between the floor slabs to fully prevent water infiltration.

Results: The intervention by WTX Foundation Repair and Earth Contact Products sealed the press pit effectively, ensuring that the facility was prepared for the fall harvest. The project's success was evident when the pit remained dry after significant rainfall, a first for the facility. This resolution not only safeguarded the upcoming production cycle but also bolstered King Mesa Gin's reputation as a leader in the organic cotton market.

Project Gallery











